# X-Ray Inspection System X-7600



### **Applications of X-Ray**

X-Ray inspection system is high-precision detection equipment. It inspects and analyzes the inner structure of the object without damage via the penetration power from X-Ray.

It has been widely applied to BGA detection, LED, SMT, semiconductor, battery, automotive electronics, ceramic products, casting, plastic, connectors, 3D image analysis, pharmaceutical products and other industries.

#### Specific application:

- 1) Defect inspection in IC encapsulation, e.g.: layer separation, cracking, void, and line integrity.
- 2) Measuring chip size, measuring line curvature, measuring the proportion of solder area of components.
- 3) Possible defects in PCB manufacturing processes, e.g.: misalignment, solder bridge and open.
- 4) SMT solder short, cold solder, component shifted, solder insufficient, solder void inspection and measurement.
- 5) Defect inspection of open, short or abnormal connections that may occur in automotive wiring harnesses and connectors.
  - 6) Inner rupture or hollow inspection in plastic or metal.
  - 7) Battery stacking uniformity, electrode welding inspection.
  - 8) Seed, biological material inspection etc.

#### **Main Functions**

Function	Advantages
X-ray tube and detector can move along Z	Detection accuracy is close to 1 µm
direction	
Voltage and current set by software	Easy to maintain, long service life.
Speed of stage moving along X-Y direction	Easy operation, training time for operator is
can be adjusted.	short.
Powerful CNC Measuring Function, can	Suitable for mass detection
test automatically, testing program can be	
edited.	
High-definition digital flat panel detector.	semi-automatic identification for OK/NG
Max Inclined Angle is 60°	products.
Large navigation view, stage will move to	Highly reliable and high-precision test.
where you click the mouse.	Greater Magnification, clearer image
Latest image processing technology, can	Suitable to different samples with large
numerically calculate the size of the defect	sizes.
and area size.	
Accurately detect insufficient solder/cold	No need to incline samples, samples can
solder and blob ratio of PCB board, can	be observed with a unique perspective
also calculate and display on the screen.	
360 ° rotation Object stage, 7-linkage	Facilitate testing samples, observed more
	easily

#### **Technical Parameters**

Items		Contents
Model		X-7600
Japan Hamamatsu X-RAY launch tube	Tube type	Closed X-ray tube
	Maximum tube	90kV (130kV Optical)
	voltage	
	Maximum tube	0.15mA
	current	
	Focal spot size	3µm
	Magnification	Geometric magnification: 200X
		System magnification: 1000X
Korea Rayence Flat	Image speed	35 fps
Panel Detector	Resolution	1500*1500
	Inclined Angle	Table 360° RotationDetector 60°
	Stage size	500mm*450mm
Cabinet Specifications	Dimension	Length: 1630mm, width: 1850mm, height: 1650mm
	Net weight	1600kg
	Input voltage	AC 110-220V (±10%) (international standard
		power supply)
X-ray leakage amount		≤1 u Sv/h
Operating system		Windows 7 Seamark3.0
Total power		2500W

# **Standard Configuration**

Name	QTY	Remark
90KV-5um Closed X Tube	1	(130kV Optical)
Object Table	1	Size: 500mm*450mm
Flat Panel Detector	1	HD
Image processor CPU	1	Complete function
LCD	1	24"

# **Object Table Control**

- 1. Speed of table can be adjusted by the spacebar: low, normal and high speed.
- 2. X, Y, Z three-axis motion and inclined angle are controlled by keyboard.
- 3. Users can control the table speed and angle programmatically.
- 4. Large navigator view, clear navigation image, table will move to where you click the mouse.
- 5. Table can rotate clockwise and anticlockwise via press 'S' and 'D'.

### **NC Programming**

- 1. Simply click the mouse and you can write programs.
- 2. Object table moves along X, Y direction for positioning; X-ray tube and detector move along Z direction for positioning.
- 3. Voltage and current set by software.
- 4. Image settings: brightness, contrast, auto gain and exposure
- 5. Users can change the pause time for program conversion.
- 6. Anti-collision system can maximize the tilt and observation of the workpieces.
- 7. Automatical analysis on diameter, proportion of cavity, area and roundness of BGA.

## **Full Automatic Testing Procedures**

Click programming without the need for operator intervention on the component can detect automatically.